

FIG. 1




FIG. 2

2/7




FIG. 3




FIG. 4

3/7




FIG. 5




FIG. 6




FIG. 7

Stress(Strain) curve- Al-alloys -2μm
strain rate: 1e-6 - sputtered by GvL




FIG. 8

6/7




FIG. 9

7/7




FIG. 10

